

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 2490	ersection ID: 24904 Main Street: PROVIDENCE_RD			Street:	PINEVILLE-MATTHEV	Location:	SW			
ADA ID: 912046B45	A51 Ramp Type: IslandPerp			Initial Pass/Fail: Fail Overall Compliance			nce: N	o Severity Score:	8.75	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
1-3-1/4 - 1.5	TIM B	Possible Solutions:		Compliance Description		Data Compliance Description			Data	
J- / BAN		Remove & Replace Entire Ran	D .	N/A	Ramp Length (in)	34.5	Yes	Ramp Slope (%)	6.8	
S. S. S.	MILL OF ELL PROPERTY		•	No	Ramp Width (in)	42.5	Yes	Ramp XSlope (%)	1.2	
	I TO RD			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	MITTERS			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
TEVILLE	1.81			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
Plus				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
1	E BALLER C	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
N/A				N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A				
	Ast Ast	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
A STALL		Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
A CONTRACTOR OF		N			X Walk 1 Direction	To N		X Walk 2 Direction	N/A	
				N/A	X Walk 1 Width (in)	103.0	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	PINEVILLE-MATTHEWS RD	_			X Walk 1 Slope (%)	1.6		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	0.8		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	3400.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	
							Yes	Surface Condition? (G/P)	Good	

1 1254