

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

55.5

48.0

5.2

4.1

11.5

3.1

N/A

Good

18.8

Intersection ID: 50762Main Street: SCOTT_CREEK_DRCross Street: BACK_CREEK_CHURCH_RDLocation:SEADA ID: 912E5AC0017ARamp Type: Combination2Initial Pass/Fail: FailOverall Compliance: NoSeverity Score:22.5

Compliance Description

N/A

N/A

N/A

N/A

N/A

No

N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Type LT

Ramp XSlope LT (%)

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

Yes

No

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Ramp XSlope RT (%)

Data

48.0

48.5

2.0

2.3

47.0 No

47.5 No

N/A N/A



Street 1 Name

Stop Condition-Street 1

Street 2 Name

Stop Condition-Street 2

N/A

Remove & Replace Entire Ramp.

Surveyor Notes:
LT RP < 5%

PROW/ADA:
Not Found, R304.5.1, R304.2.2, R304.5.3





Total Cost:



1600.00

IN/A	riale Type Li	IN/A	IN/A	riale Type IXI	IN/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To W		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	2.4		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	2.1		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A		Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstruction?	N/A
				Obstruction Type	
					N/A
			N/A	Storm Grate/Utility Hazard?	N/A
-			l	Storm Grate/Utility Type	14/4
1					N/A

Yes

Surface Condition? (G/P)

Curb Slope (%)