

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 4672	Main Street: W_MALLARD_CREEK_CHURCHCresss Street: SENATOR_ROYALL_DR								Location:	NE	
ADA ID: 915A256AB5CC	Ramp Type: IslandPerp				Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	35	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
		Possible Solutions:			Compliance Description Da			ata Compliance Description		Data	
		Remove & Replace Entir	e Ran	ıp.	N/A	Ramp Length (in)	61.0	No	Ramp Slope (%)	20.0	
AL RINAL MAL		-		•	No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	4.7	
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	a di seconda			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	12 1				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	the start				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
6 E	The second second	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
B B E	and the second s	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
W MALLARD GREEK OTU	Day Do				N/A	Shared Landing?	N/A				
		PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	A second second second	R304.5.1, R304.2.2, R304	4.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
the second	00)	. ,			N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
6	1					X Walk 1 Direction	To NE		X Walk 2 Direction	N/A	
					N/A	X Walk 1 Width (in)	120.0	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name MALLARD CREEK CH	HURCH RD					X Walk 1 Slope (%)	6.4		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	YieldSign					X Walk 1 X Slope (%)	6.7		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost:	\$	3400.00		Obstruction Type			Storm Grate/Utility Type		
							N/A			N/A	
4											

Yes Surface Condition? (G/P)

Good

