

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 23288	tersection ID: 23288 Main Street: ALEXANDER RD			Cross Street: SHAFTESBURY RD				Location:	NW
ADA ID: 91B4CFE680C1 Ramp Type: Perp			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	2	Possible Solutions:		Compliance Description			Data Compliance Description		
	S N	Remove & Replace Entire Ram	p.	N/A	Ramp Length (in)	97.0	No	Ramp Slope (%)	9.0
		-	•	Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.6
	Start Start	·		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	11			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		2		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
A A A A A A A A A A A A A A A A A A A	11 lan	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the second secon	1 and the	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
S. S.	Real P. K	2		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
655	(1) 除於(1)			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
the second se		7		N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
6.				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	A Real				X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
	Ser and a second			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name SHAFT	ESBURY RD				X Walk 1 Slope (%)	3.8		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

**Yes** Surface Condition? (G/P)

Good

