

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11153 Main Street: E\_W\_T\_HARRIS\_BV Cross Street: N\_SHARON\_AMITY\_RD Location: NE

ADA ID: 91B9A9D20F4E Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 12.5

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

N SHARON AMITY RD Signal E W T HARRIS BV Signal Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.2.2

Total Cost: \$ 3200.00

Field Measurements/Component Compilance						
Compliance Description		Data	Compli	ance	Description	Data
N/	A Ramp Length (in)	59.5	No	Ramp	Slope (%)	9.0
Ye	s Ramp Width (in)	48.0	Yes	Ramp	XSlope (%)	0.8
N/	A Flare Type LT	N/A	N/A	Flare	Type RT	N/A
N/	A Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/	A Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/	A Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/	A Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/	A Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/	A Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/	A Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/	A Shared Landing?	N/A				
N/	A Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A
N/	A Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A
N/	A Painted X Walk1?	Yes	N/A	Paint	ed X Walk2?	Yes
	X Walk 1 Direction	To NW		X Wa	lk 2 Direction	To SW
N/	A X Walk 1 Width (in)	117.5	N/A	X Wa	lk 2 Width (in)	103.0
	X Walk 1 Slope (%)	0.7		X Wa	lk 2 Slope (%)	2.8
	X Walk 1 X Slope (%)	2.3		X Wa	lk 2 X Slope (%)	1.3
N/	A Ramp inside XWalk1?	Yes	N/A	Ramp	inside XWalk2?	Yes
	Road Slope (%)	1.8	N/A	Clear	Space?	N/A
	Road X Slope (%)	0.2	N/A	Clear	Space to XWalk (in)	N/A
N/	A Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A

N/A

Storm Grate/Utility Type

Surface Condition? (G/P)

N/A

Good







**Obstruction Type**