cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 29697 Main Street: NATHANIEL_GLEN_CT						WEDDINGTON_RIDG	Location:	SE		
					Initial Pass/Fail: Fail Overall Compliance: No					
ADA ID: 91DE2D741DBF Ramp Type: BlendTrans1			IIIIIa						21.25	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:			Comp	liance Description	nce Description Data		Compliance Description	
1 - a		Remove & Replace Curb	•	•	N/A	Ramp Length (in)	54.0	Yes	BlendTrans Slope (%)	3.8
		Two New Directional Ran Equivalent.			No	Ramp Width (in)	39.0	No	BlendTrans XSlope (%)	5.5
					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	CELM -				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
- 1 55 M	ALADOL	Surveyor Notes:			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
5 <u>5</u>	DELICION				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
5	t. And the second	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
A COS WORK					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
PROW/ADA: Not Found, R304.5.1, R304.5.3					N/A	Shared Landing?	N/A			
					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
				3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				•	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To N		X Walk 2 Direction	To W	
A A A A A A A A A A A A A A A A A A A						X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	WEDDINGTON RIDGE LN	-				X Walk 1 Slope (%)	4.7		X Walk 2 Slope (%)	1.4
Stop Condition-Street 1	None					X Walk 1 X Slope (%)	2.0		X Walk 2 X Slope (%)	4.2
Street 2 Name	NATHANIEL GLEN CT				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	StopSign					Road Slope (%)	5.1		Clear Space?	N/A
	ctopolgi					Road X Slope (%)	2.9	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	2.3 N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	¢	3200.00	11/7	Obstruction Type	N/A		Storm Grate/Utility Type	11/5
		10101 0051.	Ψ	5200.00		Costruction Type	N/A		Giorni Grate/Otinity Type	N/A
							N/A			IN/A

S HILLAS

Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

11.5