

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 11430	Main Street: ALLEN_ST	Cross Street: GRACE_ST	Location: SE
ADA ID: 91E25C082FCC	Ramp Type: PerpDiag	Initial Pass/Fail: Pass	Overall Compliance: No
Severity Score: 30.25			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	

	Possible Solutions:		Compliance		Description		Data	Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter.		N/A		Ramp Length (in)		56.0	Yes	Ramp Slope (%)	5.9
	Surveyor Notes:		Yes		Ramp Width (in)		52.0	No	Ramp XSlope (%)	3.7
	N/A		N/A		Flare Type LT		None	N/A	Flare Type RT	N/A
	PROW/ADA:		N/A		Flare Slope LT (%)		N/A	N/A	Flare Slope RT (%)	N/A
	R304.5.3, R305, R302.7.2, R304.5.4		N/A		Flare Traversable LT?		N/A	N/A	Flare Traversable RT?	N/A
			Yes		Landing Length (in)		52.0	No	DWS Provided?	No
			Yes		Landing Width (in)		58.0	N/A	DWS Contrast?	No
			Yes		Landing Slope (%)		1.1	N/A	DWS Length (in)	N/A
			No		Landing X Slope (%)		4.3	N/A	DWS Full Width?	No
			N/A		Landing Curb? (Y/N)		No	N/A	DWS Offset (in)	N/A
			N/A		Shared Landing?		No			
			Yes		Gutter Ponding?		No	No	Gutter Slope (%)	14.3
			No		Gutter Lip Ht (in)		3.0	No	Gutter X Slope (%)	3.3
			N/A		Painted X Walk1?		No	N/A	Painted X Walk2?	No
					X Walk 1 Direction		To N		X Walk 2 Direction	To W
			N/A		X Walk 1 Width (in)		N/A	N/A	X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)		6.4		X Walk 2 Slope (%)	1.6
					X Walk 1 X Slope (%)		0.2		X Walk 2 X Slope (%)	5.3
			N/A		Ramp inside XWalk1?		N/A	N/A	Ramp inside XWalk2?	N/A
					Road Slope (%)		3.2	N/A	Clear Space?	Yes
					Road X Slope (%)		5.1	N/A	Clear Space to XWalk (in)	N/A
			Yes		Any Obstructions?		No	Yes	Storm Grate/Utility Hazard?	No
					Obstruction Type				Storm Grate/Utility Type	
								N/A		N/A
								Yes	Surface Condition? (G/P)	Good

Total Cost: \$ 3950.00

