


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 46748	Main Street: SUPERIOR_ST	Cross Street: NORMANS_LANDING_DR	Location: S
ADA ID: 91E79125D402	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 12.5	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		Yes	Ramp Length (in)	49.0
			N/A	Ramp Width (in)	48.0
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Flare Type RT	N/A
			N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable RT?	N/A
			N/A	DWS Provided?	N/A
Surveyor Notes: N/A			N/A	DWS Contrast?	N/A
			N/A	DWS Length (in)	N/A
			N/A	DWS Full Width?	N/A
			N/A	DWS Offset (in)	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	No
			N/A	X Walk 1 Direction	To NE
			N/A	X Walk 2 Direction	To NW
			N/A	X Walk 1 Width (in)	N/A
PROW/ADA: R304.5.3			N/A	X Walk 1 Slope (%)	1.5
			N/A	X Walk 1 X Slope (%)	2.6
			N/A	Ramp inside XWalk1?	N/A
			N/A	Ramp inside XWalk2?	N/A
			N/A	Road Slope (%)	1.5
			N/A	Road X Slope (%)	0.2
			N/A	Clear Space?	N/A
			N/A	Clear Space to XWalk (in)	N/A
			N/A	Storm Grate/Utility Hazard?	N/A
			N/A	Storm Grate/Utility Type	N/A
Total Cost:		\$ 3200.00	N/A	Obstruction Type	N/A
			Yes	Surface Condition? (G/P)	Good

