


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10027126	Main Street: GARDEN_TR	Cross Street: N/A	Location: N
ADA ID: 91F30D35189F	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
Severity Score: 22.5			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	

	Possible Solutions:		Compliance		Description		Data		Compliance		Description		Data	
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A	Ramp Length (in)	29.5	No	Ramp Slope (%)	10.7						
			No	Ramp Width (in)	43.0	No	Ramp XSlope (%)	4.9						
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A						
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A						
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A						
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A						
			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A						
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A						
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A						
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.5.1, R304.2.2, R304.5.3</p>			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A						
			N/A	Shared Landing?	N/A									
			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A						
			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A						
			N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	No						
				X Walk 1 Direction	To SE		X Walk 2 Direction	To SW						
			N/A	X Walk 1 Width (in)	55.0	N/A	X Walk 2 Width (in)	N/A						
				X Walk 1 Slope (%)	2.9		X Walk 2 Slope (%)	1.4						
				X Walk 1 X Slope (%)	0.5		X Walk 2 X Slope (%)	1.6						
			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A						
<p>Street 1 Name</p> <p>ENTRANCE</p> <p>Stop Condition-Street 2</p> <p>StopSign</p> <p>Street 2 Name</p> <p>GARDEN TR</p> <p>Stop Condition-Street 1</p> <p>None</p>				Road Slope (%)	3.0	N/A	Clear Space?	N/A						
				Road X Slope (%)	1.9	N/A	Clear Space to XWalk (in)	N/A						
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A						
				Obstruction Type			Storm Grate/Utility Type							
						N/A		N/A						
						Yes	Surface Condition? (G/P)	Good						
Total Cost:		\$	3200.00											

