cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 18533 Main St		reet: FAIRFAX_DR	Cross	Street:	MICHAEL_BAKER_PL			Location:	NE
ADA ID: 92036706B603 Ramp T		ype: PerpDiag	Initial	Initial Pass/Fail: Fail Overall Compl			iance: No Severity Score:		35
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description		Data	Data Compliance Description		Data
and the second s		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	54.0	No	Ramp Slope (%)	14.5
1. 1. 1. 1. 1. 1.		Two New Directional Ramps or		No	Ramp Width (in)	45.0	No	Ramp XSlope (%)	4.2
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
and the second				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
A second	My I Ban			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	and I am the second			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	March - Allerander	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
<u>ь ў</u>		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			10/4
and the second	Star Coleman	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
and the state of the	The A N. Mark			N/A	Gutter Lip Ht (in)	N/A		Gutter X Slope (%)	N/A
		Not Found, R304.5.1, R304.2.2, R304.5.3	1	N/A	Painted X Walk1?	N/A No	N/A	Painted X Walk2?	N/A No
				N/A	X Walk 1 Direction		N/A	X Walk 2 Direction	-
						To W			To S
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	FAIRFAX DR				X Walk 1 Slope (%)	4.0		X Walk 2 Slope (%)	0.8
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	2.7
Street 2 Name	MICHAEL BAKER PL			N/A	Ramp inside XWalk1?	N/A		Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	2.9	N/A	Clear Space?	N/A
					Road X Slope (%)	3.3	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

