cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 31504	Main Street: SUNMAN_RD				TIRANO_CT	Location:	NW		
ADA ID: 920E3FD79786	Ramp Type: BlendTrans1			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	21.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:						liance Description	Data
TITANO GI SI SI S		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	48.5		BlendTrans Slope (%)	4.4
		Two New Directional Ramps or		No	Ramp Width (in)	46.0	No	BlendTrans XSlope (%)	6.4
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		,,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To S		X Walk 2 Direction	To E
Contraction of the second second					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	TIRANO CT				X Walk 1 Slope (%)	9.0		X Walk 2 Slope (%)	2.3
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	0.3		X Walk 2 X Slope (%)	8.8
Street 2 Name	SUNMAN RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	None				Road Slope (%)	4.5		Clear Space?	N/A
					Road X Slope (%)	8.5	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

10.7