


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 9685	Main Street: EDGEWOOD_RD	Cross Street: SUSAN_ST	Location:	N
ADA ID: 9299D6CF8867	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 8.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance													
	Possible Solutions:		Compliance			Description			Data	Compliance			Description			Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)			56.0			Yes	Ramp Slope (%)			5.3		
			No	Ramp Width (in)			38.0			Yes	Ramp XSlope (%)			0.3		
			N/A	Flare Type LT			N/A			N/A	Flare Type RT			N/A		
			N/A	Flare Slope LT (%)			N/A			N/A	Flare Slope RT (%)			N/A		
			N/A	Flare Traversable LT?			N/A			N/A	Flare Traversable RT?			N/A		
			N/A	Landing Length (in)			N/A			N/A	DWS Provided?			N/A		
			N/A	Landing Width (in)			N/A			N/A	DWS Contrast?			N/A		
			N/A	Landing Slope (%)			N/A			N/A	DWS Length (in)			N/A		
			N/A	Landing X Slope (%)			N/A			N/A	DWS Full Width?			N/A		
Surveyor Notes:		N/A	N/A			N/A			N/A	DWS Offset (in)			N/A			
PROW/ADA:		R304.5.1	N/A			N/A			N/A	Gutter Ponding?			N/A			
			N/A			N/A			N/A	Gutter Lip Ht (in)			0.5			
			N/A			N/A			No	Painted X Walk2?			N/A			
						X Walk 1 Direction			To S	X Walk 2 Direction			N/A			
			N/A			X Walk 1 Width (in)			N/A	X Walk 2 Width (in)			N/A			
						X Walk 1 Slope (%)			0.3	X Walk 2 Slope (%)			N/A			
						X Walk 1 X Slope (%)			1.4	X Walk 2 X Slope (%)			N/A			
Street 1 Name		SUSAN ST	N/A			N/A			N/A	Ramp inside XWalk2?			N/A			
Stop Condition-Street 2		StopSign	N/A			N/A			N/A	Clear Space?			N/A			
Street 2 Name		N/A	N/A			N/A			N/A	Clear Space to XWalk (in)			N/A			
Stop Condition-Street 1		N/A	N/A			N/A			N/A	Storm Grate/Utility Hazard?			N/A			
Total Cost:		\$ 1850.00	Obstruction Type						N/A	Storm Grate/Utility Type			N/A			
									N/A	Yes			Surface Condition? (G/P) Good			

