

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 16342Main Street:ALLISTER_DRCross Street:E W T HARRIS BVLocation:NEADA ID: 92C92B2A21CCRamp Type:PerpDiagInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:35

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

E W T HARRIS BV None ALLISTER DR StopSign Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.2.2, R304.5.3

Total Cost: \$ 3200.00

Field Measurements/Component Compliance					
Compliance Description		Data	Com	oliance Description	Data
N/	A Ramp Length (in)	60.0	No	Ramp Slope (%)	13.4
No	Ramp Width (in)	36.0	No	Ramp XSlope (%)	3.4
N/	A Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/	A Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/	A Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/	A Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/	A Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/	A Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/	A Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/	A Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/	A Shared Landing?	N/A			
N/	A Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/	A Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/	A Painted X Walk1?	No	N/A	Painted X Walk2?	No
	X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
N/	A X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	2.7		X Walk 2 Slope (%)	3.1
	X Walk 1 X Slope (%)	3.5		X Walk 2 X Slope (%)	6.1
N/	A Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	1.5	N/A	Clear Space?	N/A
	Road X Slope (%)	5.0	N/A	Clear Space to XWalk (in)	N/A
N	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
35V060-1000000					





