

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 13406	Main Street: HOBBS_HILL_DR	Cross Street: HONEY_HURST_LN	Location: SE
ADA ID: 92ECC71F6BA0	Ramp Type: BlendTrans2	Initial Pass/Fail: Fail	Overall Compliance: No
Severity Score: 1.25			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.3

Total Cost: \$ 3200.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	83.5	Yes	BlendTrans Slope (%)	2.4
Yes	Ramp Width (in)	48.0	No	BlendTrans XSlope (%)	2.6
N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped
N/A	Flare Slope LT (%)	4.6	N/A	Flare Slope RT (%)	2.6
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	Yes
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	Yes
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	24.0
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	3.0
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	No	N/A	Gutter Slope (%)	6.5
N/A	Gutter Lip Ht (in)	0.5	N/A	Gutter X Slope (%)	1.3
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	2.7		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	1.0		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	1.0		Clear Space?	Yes
	Road X Slope (%)	2.7	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	No	N/A	Storm Grate/Utility Hazard?	No
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
			No	Curb Slope (%)	18.2

