

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|                        |                         |                          |                        |
|------------------------|-------------------------|--------------------------|------------------------|
| Intersection ID: 10198 | Main Street: FONTANA_AV | Cross Street: REMBERT_CT | Location: E            |
| ADA ID: 932379133180   | Ramp Type: Combination1 | Initial Pass/Fail: Fail  | Overall Compliance: No |
|                        |                         | Severity Score: 37.5     |                        |

#### Codes/Mitigation Info/Possible Solution

#### Field Measurements/Component Compliance



Possible Solutions:

**Remove & Replace Entire Ramp.**

Surveyor Notes:

**N/A**

PROW/ADA:

**Not Found, R304.5.3, R304.3.2**

Total Cost:

**\$ 1800.00**

| Compliance | Description              | Data  | Compliance | Description                 | Data |
|------------|--------------------------|-------|------------|-----------------------------|------|
| N/A        | Ramp Length LT (in)      | 35.0  | N/A        | Ramp Length RT (in)         | 35.0 |
| Yes        | Ramp Width LT (in)       | 48.0  | Yes        | Ramp Width RT (in)          | 48.0 |
| Yes        | Ramp Slope LT (%)        | 7.9   | No         | Ramp Slope RT (%)           | 11.7 |
| No         | Ramp XSlope LT (%)       | 3.1   | No         | Ramp XSlope RT (%)          | 2.3  |
| N/A        | Ramp Length (in)         | 60.0  | Yes        | Ramp Slope (%)              | 4.7  |
| Yes        | Ramp Width (in)          | 48.0  | No         | Ramp XSlope (%)             | 8.9  |
| N/A        | Flare Type LT            | N/A   | N/A        | Flare Type RT               | N/A  |
| N/A        | Flare Slope LT (%)       | N/A   | N/A        | Flare Slope RT (%)          | N/A  |
| N/A        | Flare Traversable LT?    | N/A   | N/A        | Flare Traversable RT?       | N/A  |
| N/A        | Landing Length (in)      | N/A   | N/A        | DWS Provided?               | N/A  |
| N/A        | Landing Width (in)       | N/A   | N/A        | DWS Contrast?               | N/A  |
| N/A        | Landing Slope (%)        | N/A   | N/A        | DWS Length (in)             | N/A  |
| N/A        | Landing X Slope (%)      | N/A   | N/A        | DWS Full Width?             | N/A  |
| N/A        | Landing Curb? (Y/N)      | N/A   | N/A        | DWS Offset (in)             | N/A  |
| N/A        | Shared Landing?          | N/A   |            |                             |      |
| N/A        | Gutter Ponding?          | N/A   | N/A        | Gutter Slope (%)            | N/A  |
| N/A        | Gutter Lip Ht (in)       | N/A   | N/A        | Gutter X Slope (%)          | N/A  |
| N/A        | Painted X Walk1?         | No    | N/A        | Painted X Walk2?            | N/A  |
|            | X Walk 1 Direction       | To SW |            | X Walk 2 Direction          | N/A  |
|            | X Walk 1 Width (in)      | N/A   |            | X Walk 2 Width (in)         | N/A  |
|            | X Walk 1 Slope (%)       | 2.9   |            | X Walk 2 Slope (%)          | N/A  |
|            | X Walk 1 X Slope (%)     | 6.0   |            | X Walk 2 X Slope (%)        | N/A  |
| N/A        | Ramp inside XWalk1?      | N/A   | N/A        | Ramp inside XWalk2?         | N/A  |
|            | Road Slope (%)           | N/A   |            | Clear Space?                | N/A  |
|            | Road X Slope (%)         | N/A   | N/A        | Clear Space to XWalk (in)   | N/A  |
|            |                          |       | N/A        | Any Obstruction?            | N/A  |
|            |                          |       |            | Obstruction Type            | N/A  |
|            |                          |       | N/A        | Storm Grate/Utility Hazard? | N/A  |
|            |                          |       |            | Storm Grate/Utility Type    | N/A  |
|            |                          |       |            |                             | N/A  |
| Yes        | Surface Condition? (G/P) | Good  |            |                             |      |
|            | Curb Slope (%)           | 16.8  |            |                             |      |

|                         |            |
|-------------------------|------------|
| Street 1 Name           | None       |
| Stop Condition-Street 1 | FONTANA_AV |
| Street 2 Name           | N/A        |
| Stop Condition-Street 2 | N/A        |

