

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

N/A

0.0

0.0

N/A

0.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

1.5

10.3

N/A

N/A

N/A

N/A

1.4

Good

Intersection ID: 10020013 Main Street: ARROWPOINT_LN Cross Street: N/A Location: W

ADA ID: 934F2E281BCB Ramp Type: Directional1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

N/A N/A

Compliance Description

Grade Break?

Flare Type RT

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset LT (in)

DWS Offset RT (in)

Gutter Slope (%)

Road Slope (%)

Clear Space?

Road X Slope (%)

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Curb Slope (%)

Storm Grate/Utility Hazard?

Gutter X Slope (%)

Flare Traversable RT?

Grade Break Slope (%)

Grade Break XSlope (%)

Data

100.0

60.0

4.9

8.3

N/A

N/A

N/A

0.0

0.0

0.0

0.0

N/A

N/A

0.0

0.0

No

To S

N/A

1.5

10.3

N/A

N/A



Street 1 Name ENTRANCE
Stop Condition-Street 1 StopSign
Street 2 Name N/A
Stop Condition-Street 2 N/A

Compliance Description Possible Solutions: N/A Ramp Length (in) Remove & Replace Entire Ramp. Yes Ramp Width (in) Yes Ramp Slope (%) No Ramp XSlope (%) N/A Flare Type LT N/A Flare Slope LT (%) Surveyor Notes: N/A Flare Traversable LT? N/A N/A Landing Length (in) N/A Landing Width (in) N/A Landing Slope (%) N/A Landing X Slope (%) PROW/ADA: N/A Landing Curb? (Y/N) R304.5.3 N/A Shared Landing? N/A **Gutter Ponding?** N/A Gutter Lip Ht (in) N/A Painted X Walk1? X Walk 1 Direction X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%)

Total Cost:





N/A

N/A

1600.00

Ramp inside XWalk1?

Any Obstructions?

Obstruction Type