

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 31765	Main Str	Main Street: FIRST_RUN_CT				PINYON_PINE_LN		Location:	w			
ADA ID: 939D68ADD3BA	Ramp Ty	Ramp Type: Combination2			Initial Pass/Fail: Fail Overall Complian				o Severity Score:	1.25		
Codes/Mitigation Info/Possible Solution						Field Measurements/Component Compliance						
	Possible Solutions:				Compliance Description			Data Compliance Description				
5.	Brok . /	Remove & Replace Ent	ire Ran	nn	N/A	Ramp Length LT (in)	67.0	N/A	Ramp Length RT (in)	72.0		
A CALL					Yes	Ramp Width LT (in)	48.0	N/A	Ramp Width RT (in)	49.0		
and the first	15 1 30				Yes	Ramp Slope LT (%)	5.4	N/A	Ramp Slope RT (%)	0.2		
	X N				No	Ramp XSlope LT (%)	3.8	N/A	Ramp XSlope RT (%)	2.4		
A A A A A A	Contra all				N/A	Ramp Length (in)	86.0	Yes	Ramp Slope (%)	5.1		
	1 AM				Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.7		
A A A A A A A A A A A A A A A A A A A	6 6 / / /	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
the second s	A G	RT RP < 5%			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
A MARCHAN AND					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
E.		PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
	6 <u>6</u>	Not Found, R304.5.3			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
	X	,			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
					N/A	Shared Landing?	N/A					
<u>k</u>					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
Street 1 Name	YieldSign				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
Stop Condition-Street 1	FIRST RUN CT				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
Street 2 Name	N/A					X Walk 1 Direction	To NE		X Walk 2 Direction	N/A		
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A		
						X Walk 1 Slope (%)	3.1		X Walk 2 Slope (%)	N/A		
						X Walk 1 X Slope (%)	3.6		X Walk 2 X Slope (%)	N/A		
		Total Cost:	\$	1600.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
						Road Slope (%)	N/A		Clear Space?	N/A		
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
				-	- Ant	TIM		N/A	Any Obstruction?	N/A		
									Obstruction Type	N/A		

- N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A
- Yes
 Surface Condition? (G/P)
 Good

 Curb Slope (%)
 14.4





