

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 27228 Main St	27228 Main Street: BALLANTYNE_COMMONS_PY Cross Street: TOM_SHORT_RD						SW
		Initial Pass		Location: o Severity Score:	22.5		
					22.5		
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance					
The Maria La State /	Possible Solutions:	Co	npliance Desc	ription Data	Comp	liance Description	Data
	Remove & Replace Entire Ramp.	N/A	1 0	()	No	Ramp Slope (%)	9.3
		No	Ramp Width	n (in) 47.0	No	Ramp XSlope (%)	3.3
A CONTRACTOR OF		N/A	Flare Type I	LT N/A	N/A	Flare Type RT	N/A
TOTES A		N/A	Flare Slope	LT (%) N/A	N/A	Flare Slope RT (%)	N/A
and an the section of		N/A	Flare Traver	rsable LT? N/A	N/A	Flare Traversable RT?	N/A
	# 12	N/A	Landing Len	ngth (in) N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:	N/A	Landing Wic	dth (in) N/A	N/A	DWS Contrast?	N/A
	N/A	N/A	Landing Slo	pe (%) N/A	N/A	DWS Length (in)	N/A
		N/A	Landing X S	slope (%) N/A	N/A	DWS Full Width?	N/A
		N/A	Landing Cur	rb? (Y/N) N/A	N/A	DWS Offset (in)	N/A
- Bart Anna		N/A	Shared Land	ding? N/A			
A AND CONTRACTOR OF THE	PROW/ADA:	N/A	Gutter Pond	ling? N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.1, R304.2.2,	N/A	Gutter Lip H	lt (in) N/A	N/A	Gutter X Slope (%)	N/A
and a state of the second s	R304.5.3	N/A	Painted X W	/alk1? No	N/A	Painted X Walk2?	N/A
and the second second			X Walk 1 Dir	rection To NW		X Walk 2 Direction	N/A
		N/A	X Walk 1 Wi	idth (in) N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name BALLANTYNE COMMONS PY			X Walk 1 Slo	ope (%) 1.1		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2 Signal			X Walk 1 X S	Slope (%) 2.6		X Walk 2 X Slope (%)	N/A
Street 2 Name N/A		N/A	Ramp inside	e XWalk1? N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 N/A			Road Slope		N/A	Clear Space?	N/A
			, Road X Slop		N/A	Clear Space to XWalk (in)	N/A
		N/A			N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 1	850.00	Obstruction			Storm Grate/Utility Type	
	•			N/A			N/A

Yes Surface Condition? (G/P)

Good

