

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 6185	Main Street: STATESVILLE_RD	Cross Street: ORR_ST	Location: NE
ADA ID: 94454D5CA1D2	Ramp Type: Directional1	Initial Pass/Fail: Pass	Overall Compliance: No
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	
Severity Score: 0			



Possible Solutions:

**Remove & Replace Entire Ramp.
Utility Present.**

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R302.7, R302.3, R402.2

Total Cost: \$ 6600.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	73.0	Yes	Grade Break?	Yes
Yes	Ramp Width (in)	69.0	Yes	Grade Break Slope (%)	4.9
Yes	Ramp Slope (%)	5.1	Yes	Grade Break XSlope (%)	1.6
Yes	Ramp XSlope (%)	0.6			
Yes	Flare Type LT	N/A	Yes	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
Yes	Landing Length (in)	59.5	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	72.0	Yes	DWS Contrast?	Yes
Yes	Landing Slope (%)	0.6	Yes	DWS Length (in)	24.0
Yes	Landing X Slope (%)	0.2	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	N/A	Yes	DWS Offset LT (in)	2.0
N/A	Shared Landing?	No	Yes	DWS Offset RT (in)	58.0
No	Gutter Ponding?	Yes	Yes	Gutter Slope (%)	1.5
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.5
N/A	Painted X Walk1?	No		Road Slope (%)	0.4
	X Walk 1 Direction	To S		Road X Slope (%)	3.1
	X Walk 1 Width (in)	N/A		Clear Space?	Yes
	X Walk 1 Slope (%)	0.4	N/A	Clear Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	3.1	No	Storm Grate/Utility Hazard?	Yes
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
Yes	Any Obstructions?	No			
	Obstruction Type		Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	16.9

GAS VAL GTR

