

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 25850	Main Str	Cross Street: CASTLEKEEP_RD					Location:	SE	
ADA ID: 9471ED05EE77		Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: No				1.25
									1.20
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	intra Dir	Possible Solutions:	Compliance Description			Data Compliance Description		Data	
	A LAN TO	Remove & Replace Entire Ramp	. N	/ A	Ramp Length (in)	107.0	N/A	Grade Break?	N/A
A AND AND AND AND AND AND AND AND AND AN	N. Branks		Y	es	Ramp Width (in)	53.0	N/A	Grade Break Slope (%)	0.0
	Market Market		Ye	es	Ramp Slope (%)	2.6	N/A	Grade Break XSlope (%)	0.0
	Providence 1 Mar		N	0	Ramp XSlope (%)	3.0			
	The second		N	/ A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
CASTLEY			N	/ A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
E CAR	RD C	Surveyor Notes:	N	/ A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		N/A	N	/ A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
	A Constant		N	/ A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
	ALC: NO		N	/ A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
	Contract Will		N	/ A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
	1. Strange Strange	PROW/ADA:	N	/ A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
		R304.5.3	N	/ A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
THE PARTY	A ME C		N	/ A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
			N	/ A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
	A +		N	/ A	Painted X Walk1?	No		Road Slope (%)	11.1
Street 1 Name	BLOCKADE CT				X Walk 1 Direction	To W		Road X Slope (%)	4.8
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	11.1	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	4.8	N/A	Storm Grate/Utility Hazard?	N/A
			N	/ A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
			Ν	/ A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	2.6

