## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



						,					
Intersection ID: 13905	Main Street: CENTRAL_AV					Cross Street: SHERIDAN_DR				Location:	Ν
ADA ID: 9497D7185D9C	Ramp Ty	Ramp Type: Combination1				Initial Pass/Fail: Fail Overall Complian				nce: No Severity Score: 10	
Co	des/Mitigation Info	Possible Solut	tion				Field Meas	urements/C	ompo	onent Compliance	
	Possible Solutions:				Compliance Description			Data Compliance Description			
Selfin , Testa	1 11/15	Remove & R	eplace Enti	re Ram	<b>p</b> .	N/A	Ramp Length LT (in)	43.0	N/A	Ramp Length RT (in)	31.0
6	8				-	Yes	Ramp Width LT (in)	60.0	Yes	Ramp Width RT (in)	60.0
III	B. Sala					Yes	Ramp Slope LT (%)	5.2	Yes	Ramp Slope RT (%)	7.1
Carlos Andread						No	Ramp XSlope LT (%)	3.1	Yes	Ramp XSlope RT (%)	1.7
						N/A	Ramp Length (in)	53.0	Yes	Ramp Slope (%)	2.8
Bernard B	1 IN Las					No	Ramp Width (in)	38.0	Yes	Ramp XSlope (%)	0.6
	1 1 mart	Surveyor Notes:				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		RP < 5%, NC	ORT SW			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	6. 1000 M	,				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
IN STUDE						N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
						N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
<u>E</u>		PROW/ADA:				N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
5		Not Found,	R304.5.1, R	304.5.3		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		,	,			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	THE WAY					N/A	Shared Landing?	N/A			
						N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	StopSign					N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	SHERIDAN DR					N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
Street 2 Name	N/A						X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
Stop Condition-Street 2	N/A						X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
							X Walk 1 Slope (%)	0.8		X Walk 2 Slope (%)	N/A
							X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	N/A
		Total Cost:		\$	1800.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
							Road Slope (%)	N/A		Clear Space?	N/A
							Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
and the second se	A. Same		Strand at		e the	1 10	and the second		N/A	Any Obstruction?	N/A
81 R	and the second	I STATE				- Josef				Obstruction Type	
			i dije								N/A
						at lose			N/A	Storm Grate/Utility Hazard?	N/A
		114								Storm Grate/Utility Type	194

Storm Grate/Utility Type
N/A
Yes Surface Condition? (G/P) Good
Curb Slope (%) 12.7





