

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 29389 Main Street: GOLD_PAN_RD Cross Street: REEDY_PLANTATION_RD Location: NE

ADA ID: 94CFA67AB36E Ramp Type: BlendTrans1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 8.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name REEDY PLANTATION RD
Stop Condition-Street 1 None
Street 2 Name GOLD PAN RD
Stop Condition-Street 2 StopSign

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1

No N/A N/A N/A N/A N/A N/A N/A N/A N/A

Compliance Description Data Compliance Description Data Ramp Length (in) Yes N/A 49.5 BlendTrans Slope (%) 3.3 47.5 Yes Ramp Width (in) BlendTrans XSlope (%) 1.0 N/A Flare Type LT N/A Flare Type RT N/A Flare Slope LT (%) N/A N/A Flare Slope RT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A Landing Length (in) N/A N/A **DWS Provided?** N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A Landing Slope (%) DWS Length (in) N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A Shared Landing? **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A Painted X Walk1? No N/A Painted X Walk2? No X Walk 1 Direction To W X Walk 2 Direction To S N/A X Walk 1 Width (in) X Walk 2 Width (in) N/A X Walk 1 Slope (%) 1.7 X Walk 2 Slope (%) 3.6 X Walk 1 X Slope (%) 4.4 X Walk 2 X Slope (%) 1.4 N/A N/A Ramp inside XWalk2? N/A Ramp inside XWalk1? Road Slope (%) 0.7 Clear Space? N/A Road X Slope (%) 2.8 N/A Clear Space to XWalk (in) N/A N/A N/A Any Obstructions? Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good No Curb Slope (%) 15.9





Total Cost:



3200.00