

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10132	Main Street: CAMPUS_ST	Cross Street: MILL_RD	Location: SE
ADA ID: 95486AAA213D	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	

	Possible Solutions:		Compliance		Description		Data	Compliance	Description		Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A		Ramp Length (in)		44.0	Yes		Ramp Slope (%)	7.4
			No		Ramp Width (in)		46.0	No		Ramp XSlope (%)	5.4
			N/A		Flare Type LT		N/A	N/A		Flare Type RT	N/A
			N/A		Flare Slope LT (%)		N/A	N/A		Flare Slope RT (%)	N/A
			N/A		Flare Traversable LT?		N/A	N/A		Flare Traversable RT?	N/A
			N/A		Landing Length (in)		N/A	N/A		DWS Provided?	N/A
			N/A		Landing Width (in)		N/A	N/A		DWS Contrast?	N/A
			N/A		Landing Slope (%)		N/A	N/A		DWS Length (in)	N/A
			N/A		Landing X Slope (%)		N/A	N/A		DWS Full Width?	N/A
Street 1 Name	MILL RD		N/A		Landing Curb? (Y/N)		N/A	N/A		DWS Offset (in)	N/A
	Stop Condition-Street 2		StopSign		Shared Landing?		N/A				
	Street 2 Name		CAMPUS ST		N/A		N/A	N/A		Gutter Ponding?	N/A
	Stop Condition-Street 1		StopSign		N/A		N/A	N/A		Gutter Lip Ht (in)	N/A
					N/A		No	N/A		Painted X Walk2?	No
							To N			X Walk 2 Direction	To W
					N/A		N/A	N/A		X Walk 2 Width (in)	N/A
										X Walk 2 Slope (%)	0.7
										X Walk 2 X Slope (%)	0.6
					N/A		N/A	N/A		Ramp inside XWalk2?	N/A
									Clear Space?	N/A	
									Clear Space to XWalk (in)	N/A	
				N/A		N/A	N/A		Storm Grate/Utility Hazard?	N/A	
									Storm Grate/Utility Type		
							N/A			N/A	
								Yes	Surface Condition? (G/P)	Good	

Surveyor Notes:	
N/A	
PROW/ADA:	
Not Found, R304.5.1, R304.5.3	

Total Cost:	\$	3200.00
-------------	----	---------

