

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10032016Main Street:MONTCLAIR_AVCross Street:N/ALocation:SWADA ID: 956653DBF1F7Ramp Type:BlendTrans2Initial Pass/Fail:FailOverall Compliance:NoSeverity Score:8.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name PROVIDENCE CIR
Stop Condition-Street 1 StopSign
Street 2 Name N/A
Stop Condition-Street 2 N/A

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:
PROVIDENCE CIR PVT

PROW/ADA:
Not Found, R304.5.1

Total Cost: \$ 3200.00

Compliance Description Data Compliance Description Data Ramp Length (in) Yes BlendTrans Slope (%) N/A 68.0 4.1 47.0 Yes No Ramp Width (in) BlendTrans XSlope (%) 1.9 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A Flare Slope LT (%) N/A N/A Flare Slope RT (%) N/A N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A Landing Length (in) N/A N/A DWS Provided? N/A N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A N/A Landing Slope (%) DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No N/A Painted X Walk2? N/A X Walk 1 Direction To E X Walk 2 Direction N/A N/A X Walk 1 Width (in) X Walk 2 Width (in) N/A X Walk 1 Slope (%) 0.1 X Walk 2 Slope (%) N/A X Walk 1 X Slope (%) 3.6 X Walk 2 X Slope (%) N/A N/A N/A Ramp inside XWalk2? N/A N/A Ramp inside XWalk1? Road Slope (%) 3.6 Clear Space? N/A N/A Road X Slope (%) 0.1 Clear Space to XWalk (in) N/A N/A N/A N/A Any Obstructions? Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good

No

Curb Slope (%)

5.3





