

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A Main Street: PROVIDENCE_RD Cross Street: N/A Location: NW **Overall Compliance: No** ADA ID: 9588D1BB71F6 Ramp Type: Perp Initial Pass/Fail: Fail Severity Score: 13.75

Codes/Mitigation Info/Possible Solution



ENTRANCE Street 1 Name Stop Condition-Street 2 None Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solutions:	<u>c</u>		
Remove & Replace Entire Ramp.			
	Y		
	N		
	N		
	N		
	N		
Surveyor Notes:	N		
N/A	N		
	N		
	N		
	N		
PROW/ADA:	N		
Not Found, R304.2.2	N		
	N		
	N		

Total Cost: 1850.00

Field Measurements/Component Compliance								
Comp	liance Description	Data	Comp	liance	Description	Data		
N/A	Ramp Length (in)	74.0	No	Ramp	Slope (%)	11.7		
Yes	Ramp Width (in)	53.0	Yes	Ramp XSlope (%)		2.3		
N/A	Flare Type LT	N/A	N/A	Flare Type RT		N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare S	Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare T	raversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS F	Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS (Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS L	ength (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS F	Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS (Offset (in)	N/A		
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutter	Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter	X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Painte	d X Walk2?	N/A		
	X Walk 1 Direction	To S		X Walk	2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk	2 Width (in)	N/A		
	X Walk 1 Slope (%)	2.9		X Walk	(2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	6.3		X Walk	(2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear S	Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear S	Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm	Grate/Utility Type			
		N/A				N/A		
			Yes	Surfac	e Condition? (G/P)	Good		





