


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 15211	Main Street: EAST_BV	Cross Street: SCOTT_AV	Location: N
ADA ID: 959C0A290064	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 13.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A	Ramp Length (in)	51.0
			Yes	Ramp Width (in)	72.0
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
			N/A	Landing Curb? (Y/N)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	N/A
			N/A	Painted X Walk1?	Yes
				X Walk 1 Direction	To SW
			N/A	X Walk 1 Width (in)	108.0
				X Walk 1 Slope (%)	4.8
				X Walk 1 X Slope (%)	0.0
			N/A	Ramp inside XWalk1?	Yes
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.2.2, R304.5.3</p>			N/A	Flare Type RT	N/A
			N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable RT?	N/A
			N/A	DWS Provided?	N/A
			N/A	DWS Contrast?	N/A
			N/A	DWS Length (in)	N/A
			N/A	DWS Full Width?	N/A
			N/A	DWS Offset (in)	N/A
			N/A	Gutter Slope (%)	N/A
			N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk2?	Yes
				X Walk 2 Direction	To SE
			N/A	X Walk 2 Width (in)	114.0
				X Walk 2 Slope (%)	0.2
				X Walk 2 X Slope (%)	4.2
			N/A	Ramp inside XWalk2?	Yes
			N/A	Clear Space?	N/A
			N/A	Clear Space to XWalk (in)	N/A
			N/A	Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	
			N/A		N/A
			Yes	Surface Condition? (G/P)	Good
Street 1 Name	EAST BV				
Stop Condition-Street 2	Signal				
Street 2 Name	SCOTT AV				
Stop Condition-Street 1	Signal				
Total Cost:	\$	3200.00			

