

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

N/A

N/A

N/A

N/A

9.7

N/A

Good

N/A

Main Street: CLARKE CREEK PY **Cross Street: BROOKINGS DR** Location: Intersection ID: 2453 NE Ramp Type: Combination2 Initial Pass/Fail: Fail **Overall Compliance: No** ADA ID: 95A029A10D8B Severity Score: 26.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

N/A

N/A

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Ramp XSlope RT (%)

Storm Grate/Utility Type

Surface Condition? (G/P)

Curb Slope (%)

Data

64.0

55.0

12.0

1.1

47.0 No

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp XSlope LT (%)



Street 1 Name StopSign Stop Condition-Street 1 **BROOKINGS DR** N/A Street 2 Name Stop Condition-Street 2 N/A Possible Solutions: Compliance Description Remove & Replace Entire Ramp. N/A Yes No Yes N/A Yes Surveyor Notes: N/A N/A N/A N/A N/A N/A PROW/ADA: N/A R304.2.2, R304.5.3, R304.3.2 N/A N/A N/A N/A N/A N/A



Total Cost:



1600.00

	1 3 ()	-		1 1 \ /	
Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	4.1
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	X Walk 1 Direction	To W		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	3.8		X Walk 2 Slope (%)	1.7
	X Walk 1 X Slope (%)	3.3		X Walk 2 X Slope (%)	4.4
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	3.5		Clear Space?	N/A
	Road X Slope (%)	0.7	N/A	Clear Space to XWalk (in)	N/A
	The state of the s		N/A	Any Obstruction?	N/A
	4			Obstruction Type	
	A Committee of the Comm				N/A
			N/A	Storm Grate/Utility Hazard?	N/A

Yes