

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14182 Main Street: E\_PARK\_AV Cross Street: LYNDHURST\_AV Location: N

ADA ID: 95D1FA494363 Ramp Type: Combination2 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 21.25

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name

Stop Condition-Street 1

Street 2 Name

None

E PARK AV

N/A

Stop Condition-Street 2

N/A

Possible Solutions:
Remove & Replace Entire Ramp.

Surveyor Notes:
N/A

PROW/ADA:
Not Found, R304.5.1, R304.5.3

Total Cost: \$ 1600.00

Compliance Description		Data	Comp	liance Description	Data
N/A	Ramp Length LT (in)	72.0	N/A	Ramp Length RT (in)	N/A
Yes	Ramp Width LT (in)	60.0	N/A	Ramp Width RT (in)	N/A
Yes	Ramp Slope LT (%)	5.8	N/A	Ramp Slope RT (%)	N/A
Yes	Ramp XSlope LT (%)	0.6	N/A	Ramp XSlope RT (%)	N/A
N/A	Ramp Length (in)	54.0	Yes	Ramp Slope (%)	4.6
No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	6.0
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	111.0		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	5.5		X Walk 2 Slope (%)	N/A

2.3

Yes

N/A

N/A

N/A

N/A

N/A

N/A

Yes

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Any Obstruction?

**Obstruction Type** 

Curb Slope (%)

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Good

21.6







N/A