


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 9551	Main Street: EASTWAY_DR	Cross Street: HOWIE_CR	Location: SW
ADA ID: 95E0AFB9C750	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 35	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance			
	Possible Solutions:		Compliance	Description	Data	Compliance
	Remove & Replace Entire Ramp.		No	Ramp Length (in)	57.5	No
			No	Ramp Width (in)	46.0	No
			N/A	Flare Type LT	N/A	N/A
			N/A	Flare Slope LT (%)	N/A	N/A
			N/A	Flare Traversable LT?	N/A	N/A
			N/A	Landing Length (in)	N/A	N/A
			N/A	Landing Width (in)	N/A	N/A
			N/A	Landing Slope (%)	N/A	N/A
			N/A	Landing X Slope (%)	N/A	N/A
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.5.1, R304.2.2, R304.5.3</p>			N/A	Flare Type RT	N/A	N/A
			N/A	Flare Slope RT (%)	N/A	N/A
			N/A	Flare Traversable RT?	N/A	N/A
			N/A	DWS Provided?	N/A	N/A
			N/A	DWS Contrast?	N/A	N/A
			N/A	DWS Length (in)	N/A	N/A
			N/A	DWS Full Width?	N/A	N/A
			N/A	DWS Offset (in)	N/A	N/A
			N/A	Gutter Ponding?	N/A	N/A
			N/A	Gutter Lip Ht (in)	N/A	N/A
<p>Total Cost:</p> <p>\$ 1850.00</p>			No	Painted X Walk1?	N/A	N/A
			To N	X Walk 1 Direction	N/A	N/A
			N/A	X Walk 1 Width (in)	N/A	N/A
			3.8	X Walk 1 Slope (%)	N/A	N/A
			2.5	X Walk 1 X Slope (%)	N/A	N/A
			N/A	Ramp inside XWalk1?	N/A	N/A
			N/A	Road Slope (%)	N/A	N/A
			N/A	Road X Slope (%)	N/A	N/A
			N/A	Any Obstructions?	N/A	N/A
			N/A	Obstruction Type	N/A	N/A
			N/A	Storm Grate/Utility Hazard?	N/A	N/A
			N/A	Storm Grate/Utility Type	N/A	N/A
			Yes	Surface Condition? (G/P)	Good	Good

