

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 10021903 Main Street: BROOKDALE AV **Cross Street: N/A** Location: Ε ADA ID: 95E8B844962B Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 10

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1 Possible Solutions: Equivalent. Surveyor Notes: N/A PROW/ADA:

**ENTRANCE** StopSign **BROOKDALE AV** None

Remove & Replace Curb Ramp With Two New Directional Ramps or Not Found, R304.5.1, R304.5.3

Total Cost: 3200.00

Compliance Description		Data	Compliance		Description	Data
N/A	Ramp Length (in)	76.0	Yes	Ramp Slope (%)		5.9
No	Ramp Width (in)	46.0	No	Ramp XSlope (%)		3.2
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	No
	X Walk 1 Direction	To NE		X Wa	lk 2 Direction	To NW
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
	X Walk 1 Slope (%)	0.4		X Wa	lk 2 Slope (%)	4.7
	X Walk 1 X Slope (%)	1.5		X Wa	lk 2 X Slope (%)	0.4
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	inside XWalk2?	N/A
	Road Slope (%)	0.9	N/A	Clear	Space?	N/A
	Road X Slope (%)	1.9	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A
	Obstruction Type			Storn	n Grate/Utility Type	
		N/A				N/A

Surface Condition? (G/P)

Good





