

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

13.6

0.9

Good

Cross Street: CHARLOTTETOWNE AV Intersection ID: 50041 Main Street: METROPOLITAN AV Location: NW **ADA ID: 9614ACEB1C27** Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 33.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

No

Yes

Compliance Description

Ramp Slope (%)

Data

64.0

47.0



METROPOLITAN AV Street 1 Name Stop Condition-Street 2 Signal N/A Street 2 Name Stop Condition-Street 1 N/A

Possible Solution		Field Me
Possible Solutions:	Comp	liance Description
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)
•	No	Ramp Width (in)
	N/A	Flare Type LT
	N/A	Flare Slope LT (%)
	N/A	Flare Traversable LT
	N/A	Landing Length (in)
Surveyor Notes:	N/A	Landing Width (in)
N/A	N/A	Landing Slope (%)
	N/A	Landing X Slope (%
	N/A	Landing Curb? (Y/N
	N/A	Shared Landing?
PROW/ADA:	N/A	Gutter Ponding?
R304.5.1, R304.2.2	N/A	Gutter Lip Ht (in)
	N/A	Painted X Walk1?
		X Walk 1 Direction
	N/A	X Walk 1 Width (in)
		X Walk 1 Slope (%)
		X Walk 1 X Slope (%
	N/A	Ramp inside XWalk
		Road Slope (%)
		Daniel V Clara (0/)

- TO TO			
			1
到人			
			3/3
	中门口	419	111111

Total Cost:



1850.00



Ramp XSlope (%) Ramp Width (in) N/A Flare Type LT N/A Flare Type RT N/A N/A N/A Flare Slope RT (%) N/A Flare Slope LT (%) Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A N/A **DWS Provided?** N/A Landing Length (in) Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A Landing Slope (%) DWS Length (in) N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A Shared Landing? **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A Painted X Walk1? Yes N/A Painted X Walk2? N/A X Walk 1 Direction To E X Walk 2 Direction N/A 97.0 N/A X Walk 2 Width (in) X Walk 1 Width (in) N/A X Walk 1 Slope (%) X Walk 2 Slope (%) N/A 3.4 X Walk 1 X Slope (%) 1.2 X Walk 2 X Slope (%) N/A Ramp inside XWalk1? N/A Ramp inside XWalk2? Yes N/A Road Slope (%) N/A N/A Clear Space? N/A N/A Road X Slope (%) N/A Clear Space to XWalk (in) N/A Any Obstructions? N/A N/A N/A Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A

Yes

Surface Condition? (G/P)