

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Obstruction Type

Curb Slope (%)

N/A

Yes

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

N/A

N/A

N/A

Good

12.8

	•		-					
Intersection ID: 52893 Main	Main Street: TWITTER_LN		eet:	SANCTUARY_PL	Location:	SE		
ADA ID: 963A525912D7 Ramp	Ramp Type: Combination2		Initial Pass/Fail: Fail Overall Com			npliance: No Severity Score:		12.5
Codes/Mitigation I	nfo/Possible Solution			Field Measure	ments/C	ompo	nent Compliance	
	Possible Solutions:	(Compliance Description			Data Compliance Description		
	Remove & Replace Entire Ram	-	I/A	Ramp Length LT (in)	26.5	N/A	Ramp Length RT (in)	N/A
			′es	Ramp Width LT (in)	59.5		Ramp Width RT (in)	N/A
	No. 1	۲	′es	Ramp Slope LT (%)	6.7	N/A	Ramp Slope RT (%)	N/A
		۲	'es	Ramp XSlope LT (%)	0.5	N/A	Ramp XSlope RT (%)	N/A
the second secon		1	A/A	Ramp Length (in)	99.5	Yes	Ramp Slope (%)	6.7
		١	/es	Ramp Width (in)	48.0	No	Ramp XSlope (%)	5.6
	Surveyor Notes:	٩	I/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	N/A	٩	A/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		٩	I/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		٩	A/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		٩	A/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	PROW/ADA:	٩	I/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
ANGHANUTED IN SUNSHITTE	Not Found, R304.5.3	٩	I/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
The second	0	٩	I/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
6.		٩	I/A	Shared Landing?	N/A			
	L A	٩	I/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name StopSig	IN	N	I/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1 SANCTUARY F	PL	٩	I/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
Street 2 Name N	Ά			X Walk 1 Direction	To W		X Walk 2 Direction	N/A
Stop Condition-Street 2 N	Ά			X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
				X Walk 1 Slope (%)	2.0		X Walk 2 Slope (%)	N/A
				X Walk 1 X Slope (%)	4.8		X Walk 2 X Slope (%)	N/A
	Total Cost: \$	1600.00	I/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
				Road Slope (%)	N/A		Clear Space?	N/A
				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			- March			N/A	Any Obstruction?	N/A





