

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 23740 Main Street: PARK_RD Cross Street: SMITHFIELD_CHURCH_RD Location: NW ADA ID: 96AF61FD053C Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 13.75

Codes/Mitigation Info/Possible Solution



SMITHFIELD CHURCH RD Street 1 Name Stop Condition-Street 2 Signal Street 2 Name **PARK RD** Stop Condition-Street 1 Signal

Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Restripe Crosswalk. Surveyor Notes: N/A PROW/ADA: R304.2.2, R304.5.3

Total Cost: 3400.00

Field Measurements/Component Compliance						
	Compliance Description		Data	Comp	oliance Description	Data
	N/A	Ramp Length (in)	60.0	No	Ramp Slope (%)	9.0
	Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	4.1
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	N/A	Shared Landing?	N/A			
	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes
		X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
	N/A	X Walk 1 Width (in)	104.0	N/A	X Walk 2 Width (in)	100.0
		X Walk 1 Slope (%)	0.8		X Walk 2 Slope (%)	7.1
		X Walk 1 X Slope (%)	7.1		X Walk 2 X Slope (%)	2.1
	N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	No
		Road Slope (%)	3.9	N/A	Clear Space?	N/A
		Road X Slope (%)	8.8	N/A	Clear Space to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Obstruction Type			Storm Grate/Utility Type	
			N/A			N/A
				Yes	Surface Condition? (G/P)	Good
F		4 6				





