


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 2581	Main Street: COLERIDGE_CT	Cross Street: FAIRVISTA_DR	Location: SE
ADA ID: 96B2C50D1AE9	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 21.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		Yes	Ramp Slope (%)	5.3
			No	Ramp XSlope (%)	5.1
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Flare Traversable RT?	N/A
			N/A	DWS Provided?	N/A
			N/A	DWS Contrast?	N/A
			N/A	DWS Length (in)	N/A
			N/A	DWS Full Width?	N/A
			N/A	DWS Offset (in)	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	N/A
			No	Painted X Walk1?	No
			To NW	X Walk 2 Direction	To SW
			N/A	X Walk 2 Width (in)	N/A
			2.6	X Walk 2 Slope (%)	2.7
			3.0	X Walk 2 X Slope (%)	3.9
			N/A	Ramp inside XWalk2?	N/A
			4.7	Clear Space?	N/A
			3.0	Clear Space to XWalk (in)	N/A
			N/A	Storm Grate/Utility Hazard?	N/A
			N/A	Storm Grate/Utility Type	N/A
			N/A	Surface Condition? (G/P)	Good
Surveyor Notes:					
N/A					
PROW/ADA:					
R304.5.1, R304.5.3					
Total Cost:			\$	3200.00	

Street 1 Name	FAIRVISTA DR
Stop Condition-Street 2	None
Street 2 Name	COLERIDGE CT
Stop Condition-Street 1	StopSign

