


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 6609	Main Street: FIRESTONE_DR	Cross Street: LIGHTSPUN_LN	Location: NW
ADA ID: 96B3B56AB404	Ramp Type: Perp	Initial Pass/Fail: Pass	Overall Compliance: No Severity Score: 0

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	28.5	Yes	Ramp Slope (%)	5.1
			Yes	Ramp Width (in)	59.0	Yes	Ramp XSlope (%)	1.9
			N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	5.4	Yes	Flare Slope RT (%)	4.3
			N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	Yes
			Yes	Landing Length (in)	101.0	Yes	DWS Provided?	Yes
			Yes	Landing Width (in)	48.0	Yes	DWS Contrast?	Yes
			Yes	Landing Slope (%)	1.3	Yes	DWS Length (in)	24.0
			Yes	Landing X Slope (%)	0.1	Yes	DWS Full Width?	Yes
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R305.2</p>			N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	4.0
			N/A	Shared Landing?	No			
			Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	0.2
			Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.8
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
				X Walk 1 Direction	To S		X Walk 2 Direction	N/A
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
				X Walk 1 Slope (%)	0.2		X Walk 2 Slope (%)	N/A
				X Walk 1 X Slope (%)	0.1		X Walk 2 X Slope (%)	N/A
			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
<p>Total Cost:</p> <p>\$ 1850.00</p>				Road Slope (%)	N/A	N/A	Clear Space?	Yes
				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
				Obstruction Type			Storm Grate/Utility Type	
						N/A		N/A
						Yes	Surface Condition? (G/P)	Good

