

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

51.0

35.0

2.6

3.3

7.9

6.1

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Intersection ID: 9296 Main Street: EDDLEMAN RD **Cross Street: THOMASBORO DR** Location: N/A Initial Pass/Fail: Fail **Overall Compliance: No** 42.5 ADA ID: 97372BBA0E26 Ramp Type: Combination1 **Severity Score:**

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

No

Yes

No

Yes

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Flare Traversable RT?

Flare Type RT

Ramp XSlope RT (%)

Data

60.0

35.0

10.0

4.2

61.0

47.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)



Street 1 Name None THOMASBORO DR Stop Condition-Street 1 Street 2 Name N/A Stop Condition-Street 2 N/A Possible Solutions: Compliance Description N/A Remove & Replace Entire Ramp. No No No N/A No Surveyor Notes: N/A NO RT SW, RT RP < 5% N/A N/A N/A N/A PROW/ADA: N/A R304.5.1, R304.5.1, R304.5.3, N/A R304.3.2 N/A N/A N/A N/A N/A



Total Cost:



1800.00

N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	6.4		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	5.9		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A		Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
=			N/A	Any Obstruction?	N/A
				Obstruction Type	
1					N/A
			N/A	Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	IV/A
1	The A				N/A
			Yes	Surface Condition? (G/P)	Good
				Curb Slope (%)	2.6

