

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 5514Main Street:SUNSET_RDCross Street:MILHAVEN_LNLocation:SWADA ID: 97829C28E8C6Ramp Type:PerpInitial Pass/Fail:PassOverall Compliance:NoSeverity Score:12.5

Codes/Mitigation Info/Possible Solution



	The second secon
Street 1 Name	MILHAVEN LN
Stop Condition-Street 2	Signal
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Cooldic Colution				
Possible Solutions:				
Remove & Replace Entire Ramp.				
Surveyor Notes:				
N/A				
DDOWADA.				
PROW/ADA:				
Not Found, R304.2.1, R304.2.2-Perp,				
R304.3.2-Para, R304.5.3, R305.1.4, R305.2				
1000.2				

Total Cost:	\$ 1850.0

Field Measurements/Component Compliance							
Comp	liance Description	Data	Comp	liance Description	Data		
N/A	Ramp Length (in)	89.0	Yes	Ramp Slope (%)	7.8		
Yes	Ramp Width (in)	54.0	Yes	Ramp XSlope (%)	1.3		
N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	6.8	Yes	Flare Slope RT (%)	6.0		
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	Yes		
No	Landing Length (in)	N/A	Yes	DWS Provided?	Yes		
No	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes		
No	Landing Slope (%)	N/A	Yes	DWS Length (in)	24.5		
No	Landing X Slope (%)	N/A	No	DWS Full Width?	No		
N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	3.5		
N/A	Shared Landing?	No					
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	3.8		
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.7		
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	То Е		X Walk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	3.6		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	1.1		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	Yes		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		





