


Intersection ID: 13706	Main Street: CRADDOCK_AV	Cross Street: MAYFAIR_AV	Location:	NE
ADA ID: 97A1D8DD4326	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 8.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance										
	Possible Solutions:					Compliance			Description			Data	
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.					N/A			Ramp Length (in)			50.0	
						No			Ramp Width (in)			41.5	
						N/A			Flare Type LT			N/A	
						N/A			Flare Slope LT (%)			N/A	
						N/A			Flare Traversable LT?			N/A	
						N/A			Landing Length (in)			N/A	
						N/A			Landing Width (in)			N/A	
						N/A			Landing Slope (%)			N/A	
						N/A			Landing X Slope (%)			N/A	
					N/A			Landing Curb? (Y/N)			N/A		
					N/A			Shared Landing?			N/A		
					N/A			Gutter Ponding?			N/A		
					N/A			Gutter Lip Ht (in)			N/A		
					N/A			Painted X Walk1?			No		
								X Walk 1 Direction			To W		
					N/A			X Walk 1 Width (in)			N/A		
								X Walk 1 Slope (%)			2.8		
								X Walk 1 X Slope (%)			0.5		
					N/A			Ramp inside XWalk1?			N/A		
								Road Slope (%)			4.0		
								Road X Slope (%)			2.6		
					N/A			Any Obstructions?			N/A		
								Obstruction Type					
											N/A		
											Yes		
											Surface Condition? (G/P)		
											Good		

