


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 27350	Main Street: BALLANVILLA_DR	Cross Street: BALLANTYNE_TRACE_CT	Location: NW
ADA ID: 97B6BAB3D866	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 26.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
 <p>Street 1 Name BALLANVILLE DR</p> <p>Stop Condition-Street 2 StopSign</p> <p>Street 2 Name BALLANTYNE TRACE CT</p> <p>Stop Condition-Street 1 None</p>	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		No	Ramp Length (in)	52.0
			Yes	Ramp Width (in)	66.0
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
			N/A	Landing Curb? (Y/N)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	N/A
			No	Painted X Walk1?	N/A
			To S	X Walk 1 Direction	To E
			N/A	X Walk 1 Width (in)	N/A
			2.9	X Walk 1 Slope (%)	12.0
			8.9	X Walk 1 X Slope (%)	1.9
			N/A	Ramp inside XWalk1?	N/A
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>R304.2.2, R304.5.3</p>			N/A	Ramp inside XWalk2?	N/A
			3.0	Road Slope (%)	N/A
			8.8	Road X Slope (%)	N/A
			N/A	Any Obstructions?	N/A
				Obstruction Type	
			N/A		N/A
			Yes	Surface Condition? (G/P)	Good
Total Cost:		\$ 3200.00			

