


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 14337	Main Street: BERKELEY_AV	Cross Street: E_MOREHEAD_ST	Location: SW
ADA ID: 985D75CE7FB9	Ramp Type: Directional1	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 12.5	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance			
	Possible Solutions:		<b>Compliance</b>	<b>Description</b>	<b>Data</b>	
	<b>Remove &amp; Replace Entire Ramp.</b>		<b>N/A</b>	Ramp Length (in)	<b>30.0</b>	<b>N/A</b>
			<b>Yes</b>	Ramp Width (in)	<b>54.0</b>	<b>N/A</b>
			<b>Yes</b>	Ramp Slope (%)	<b>0.8</b>	<b>N/A</b>
			<b>No</b>	Ramp XSlope (%)	<b>5.2</b>	<b>N/A</b>
			<b>N/A</b>	Flare Type LT	<b>N/A</b>	<b>N/A</b>
			<b>N/A</b>	Flare Slope LT (%)	<b>N/A</b>	<b>N/A</b>
			<b>N/A</b>	Flare Traversable LT?	<b>N/A</b>	<b>N/A</b>
			<b>N/A</b>	Landing Length (in)	<b>0.0</b>	<b>N/A</b>
			<b>N/A</b>	Landing Width (in)	<b>0.0</b>	<b>N/A</b>
			<b>N/A</b>	Landing Slope (%)	<b>0.0</b>	<b>N/A</b>
			<b>N/A</b>	Landing X Slope (%)	<b>0.0</b>	<b>N/A</b>
			<b>N/A</b>	Landing Curb? (Y/N)	<b>N/A</b>	<b>N/A</b>
			<b>N/A</b>	Shared Landing?	<b>N/A</b>	<b>N/A</b>
			<b>N/A</b>	Gutter Ponding?	<b>0.0</b>	<b>N/A</b>
			<b>N/A</b>	Gutter Lip Ht (in)	<b>0.0</b>	<b>N/A</b>
			<b>N/A</b>	Painted X Walk1?	<b>No</b>	<b>N/A</b>
				X Walk 1 Direction	<b>To NW</b>	<b>N/A</b>
				X Walk 1 Width (in)	<b>N/A</b>	<b>N/A</b>
				X Walk 1 Slope (%)	<b>4.9</b>	<b>N/A</b>
				X Walk 1 X Slope (%)	<b>5.0</b>	<b>N/A</b>
<p>Surveyor Notes:</p> <p><b>N/A</b></p>			<b>N/A</b>	Ramp inside XWalk1?	<b>N/A</b>	<b>N/A</b>
			<b>N/A</b>	Any Obstructions?	<b>N/A</b>	<b>N/A</b>
<p>PROW/ADA:</p> <p><b>R304.5.3</b></p>				Obstruction Type		<b>Yes</b>
						<b>N/A</b>
Total Cost:			<b>\$</b>	<b>1600.00</b>		<b>Good</b>
						<b>10.3</b>

Street 1 Name	BERKELEY AV
Stop Condition-Street 1	None
Street 2 Name	N/A
Stop Condition-Street 2	N/A

