


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 46810	Main Street: ARBOR_VISTA_DR	Cross Street: CLAUDE_FREEMAN_DR	Location:	N
ADA ID: 98A3A0E861EB	Ramp Type: Combination1	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 26.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance							
	Possible Solutions:		<b>Compliance</b>	<b>Description</b>	<b>Data</b>	<b>Compliance</b>	<b>Description</b>	<b>Data</b>		
	<b>Remove &amp; Replace Entire Ramp.</b>		N/A	Ramp Length LT (in)	60.0	N/A	Ramp Length RT (in)	76.0		
			Yes	Ramp Width LT (in)	48.0	Yes	Ramp Width RT (in)	50.0		
			Yes	Ramp Slope LT (%)	4.3	No	Ramp Slope RT (%)	9.6		
			Yes	Ramp XSlope LT (%)	1.1	Yes	Ramp XSlope RT (%)	0.3		
			N/A	Ramp Length (in)	47.0	No	Ramp Slope (%)	17.8		
			Yes	Ramp Width (in)	57.0	No	Ramp XSlope (%)	3.5		
	Surveyor Notes:		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
	<b>LT RP &lt; 5%</b>		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
PROW/ADA:		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A			
<b>R304.2.2, R304.5.3, R304.3.2</b>		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A			
		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A			
		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A			
		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A			
		N/A	Shared Landing?	N/A						
		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A			
		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A			
		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A			
			X Walk 1 Direction	To E		X Walk 2 Direction	N/A			
						X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)	4.4		X Walk 2 Slope (%)	N/A
						X Walk 1 X Slope (%)	3.6		X Walk 2 X Slope (%)	N/A
		Total Cost:			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
						Road Slope (%)	N/A		Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
								N/A	Any Obstruction?	N/A
									Obstruction Type	N/A
								N/A	Storm Grate/Utility Hazard?	N/A
									Storm Grate/Utility Type	N/A
					Yes	Surface Condition? (G/P)	Good			
						Curb Slope (%)	N/A			

Street 1 Name

Stop Condition-Street 1

Street 2 Name

Stop Condition-Street 2

YieldSign

CLAUDE FREEMAN DR

N/A

N/A

Total Cost:

\$

1800.00

