


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 7784	Main Street: MASSEY_CT	Cross Street: SPRING_GARDEN_LN	Location: NW
ADA ID: 98B8890B2F2D	Ramp Type: Combination1	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 10	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length LT (in)	14.5
			Yes	Ramp Width LT (in)	48.0
			Yes	Ramp Slope LT (%)	3.3
			No	Ramp XSlope LT (%)	2.3
			N/A	Ramp Length (in)	48.0
			No	Ramp Width (in)	38.5
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
<p>Surveyor Notes:</p> <p>LT RP < 5%</p> <p>PROW/ADA:</p> <p>Not Found, R304.5.1, R304.5.3</p>			N/A	Ramp Slope RT (%)	5.1
			No	Ramp XSlope RT (%)	3.1
			Yes	Ramp Slope (%)	5.0
			No	Ramp XSlope (%)	3.1
			N/A	Flare Type RT	N/A
			N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable RT?	N/A
			N/A	DWS Provided?	N/A
			N/A	DWS Contrast?	N/A
			N/A	DWS Length (in)	N/A
			N/A	DWS Full Width?	N/A
			N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	N/A
			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To S
				X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	2.1
				X Walk 1 X Slope (%)	1.6
			N/A	Ramp inside XWalk1?	N/A
				Road Slope (%)	N/A
				Road X Slope (%)	N/A
			N/A	Ramp inside XWalk2?	N/A
				Clear Space?	N/A
			N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstruction?	N/A
				Obstruction Type	N/A
			N/A	Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	N/A
			Yes	Surface Condition? (G/P)	Good
				Curb Slope (%)	23.0

Street 1 Name	StopSign
Stop Condition-Street 1	MASSEY CT
Street 2 Name	N/A
Stop Condition-Street 2	N/A

Total Cost: \$ 1800.00

