


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 18315	Main Street: ADDISON_DR	Cross Street: LYTTLETON_DR	Location:	N
ADA ID: 996D14E899BE	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 22.5

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance			
 <p>Possible Solutions:</p> <p>Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.</p> <p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.5.1, R304.2.2, R304.5.3</p>	Total Cost:		\$	3200.00		
	Street 1 Name	ADDISON DR		Street 2 Name	LYTTLETON DR	
	Stop Condition-Street 2	None		Stop Condition-Street 1	StopSign	
	Compliance	Description	Data	Compliance	Description	Data
	N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	10.2
	No	Ramp Width (in)	45.8	No	Ramp XSlope (%)	3.0
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	N/A	Shared Landing?	N/A	N/A	Gutter Slope (%)	N/A
	N/A	Gutter Ponding?	N/A	N/A	Gutter X Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Painted X Walk2?	No
	N/A	Painted X Walk1?	No	N/A	X Walk 2 Direction	To SE
	N/A	X Walk 1 Direction	To SW	N/A	X Walk 2 Width (in)	N/A
	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Slope (%)	2.2
	N/A	X Walk 1 Slope (%)	0.9	N/A	X Walk 2 X Slope (%)	1.4
	N/A	X Walk 1 X Slope (%)	1.4	N/A	Ramp inside XWalk2?	N/A
	N/A	Ramp inside XWalk1?	N/A	N/A	Clear Space?	N/A
	N/A	Road Slope (%)	1.0	N/A	Clear Space to XWalk (in)	N/A
	N/A	Road X Slope (%)	1.1	N/A	Storm Grate/Utility Hazard?	N/A
	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Type	N/A
	N/A	Obstruction Type	N/A	N/A	Surface Condition? (G/P)	Good

