


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 4180	Main Street: DAVID COX RD	Cross Street: HARRIS POINTE DR	Location: NE
ADA ID: 996E7F98D8C1	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 46.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	9.9
			No	Ramp Width (in)	46.0	No	Ramp XSlope (%)	14.6
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
Street 1 Name	DAVID COX RD		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	Stop Condition-Street 2		N/A	Shared Landing?	N/A			
	Street 2 Name		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Stop Condition-Street 1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To W		X Walk 2 Direction	To S
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
				X Walk 1 Slope (%)	6.3		X Walk 2 Slope (%)	0.9
				X Walk 1 X Slope (%)	3.8		X Walk 2 X Slope (%)	8.6
			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
			Road Slope (%)	7.4	N/A	Clear Space?	N/A	
			Road X Slope (%)	3.9	N/A	Clear Space to XWalk (in)	N/A	
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
			Obstruction Type			Storm Grate/Utility Type		
					N/A		N/A	
					Yes	Surface Condition? (G/P)	Good	

Total Cost: \$ 3200.00

