cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 30444 Main S	Main Street: NANNYBERRY_LN		et:	TABCAT_CT	Location:	NE			
ADA ID: 996E9CC5CDDF Ramp	A ID: 996E9CC5CDDF Ramp Type: PerpDiag		s/Fa	il: Fail Overall (o Severity Score:	8.75			
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	Possible Solutions:	<u>Co</u>	Compliance Description			Data Compliance Description		Data	
	Remove & Replace Curb Ramp W	/ith N/.	Ά	Ramp Length (in)	45.0	Yes	Ramp Slope (%)	7.3	
	Two New Directional Ramps or Equivalent.	No	D	Ramp Width (in)	45.5	Yes	Ramp XSlope (%)	0.8	
		N//	Ά	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
		N/.	Α	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
		N/.	Α	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
		N/.	Α	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	Surveyor Notes:	N/.	Α	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	N/A	N/.	Ά	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
		N/	Α	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	-	N/.	Α	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
N ATT AT A THE		N/.	Α	Shared Landing?	N/A				
	PROW/ADA:	N/	Α	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	Not Found, R304.5.1	N//	Α	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
		N/	Α	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
				X Walk 1 Direction	To NW		X Walk 2 Direction	To SW	
		N/	Α	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name NANNYBERRY LI	 N			X Walk 1 Slope (%)	0.1		X Walk 2 Slope (%)	1.3	
Stop Condition-Street 2 Non	9			X Walk 1 X Slope (%)	0.3		X Walk 2 X Slope (%)	0.7	
Street 2 Name TABCAT C	r	N/.	Α	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1 StopSig	1			Road Slope (%)	0.6	N/A	Clear Space?	N/A	
				Road X Slope (%)	1.2	N/A	Clear Space to XWalk (in)	N/A	
		N/	/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type		
					N/A			N/A	

Yes Surface Condition? (G/P)

Good

