

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

6.3

3.5

N/A

Good

Intersection ID: 24904 Main Street: PROVIDENCE RD Cross Street: PINEVILLE-MATTHEWS RD Location: NW ADA ID: 99865563E2CA Ramp Type: IslandPerp Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 18.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance Data

34.5

35.0

N/A

Yes

To E

102.5

0.2

1.4

Yes

N/A

N/A

N/A

N/A

Yes

No

N/A

Yes

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road X Slope (%)

Any Obstructions?

Obstruction Type

Flare Traversable LT?

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

Clear Space?

Flare Traversable RT?



PROVIDENCE RD Street 1 Name Stop Condition-Street 2 Signal N/A Street 2 Name Stop Condition-Street 1 N/A

Possible Solutions:	Compl	Compliance Description		
Remove & Replace Entire Ramp.	N/A	I/A Ramp Length (in)		
·	No	Ram	p Width (in)	
	N/A	Flare Type LT		
	N/A	Flare	e Slope LT (%)	
	N/A	Flare	Traversable L	
	N/A	Land	ing Length (in)	
Surveyor Notes:	N/A	Land	ing Width (in)	
N/A	N/A	Land	ing Slope (%)	
	N/A	Land	ing X Slope (%	
	N/A	Land	ing Curb? (Y/N	
	N/A	Shar	ed Landing?	
PROW/ADA:	N/A	Gutte	er Ponding?	
Not Found, R304.5.1, R304.5.3	N/A	Gutte	er Lip Ht (in)	
	N/A	Paint	ted X Walk1?	
		X Wa	alk 1 Direction	
	N/A	X Wa	alk 1 Width (in)	
		X Wa	alk 1 Slope (%)	
		X Wa	alk 1 X Slope (%	
	N/A	Ram	p inside XWalk′	
		Road	d Slope (%)	





Total Cost:



N/A

3400.00