

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 4171	Main Street: CONNERY_CT			eet:	OLD_SUGAR_CREEK	Location:	SE		
ADA ID: 9995015160F4				Initial Pass/Fail: Fail Overall Compliance: No					8.75
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
Possible Solutions:								Data	
and the second	A AN AN	1		/A	Ramp Length (in)	47.5	Yes	Ramp Slope (%)	<u>6.6</u>
The set a start life	114 221	Remove & Replace Entire Ramp.	N/		Ramp Width (in)	47.5 37.0	Yes	Ramp XSlope (%)	0.0 0.4
A COLORADOR		2	N/		,	37.0 N/A	N/A		0.4 N/A
					Flare Type LT			Flare Type RT	
	/		N/		Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	NNERY_CT		N/		Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/		Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:	N/		Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
en e		N/A	N/	/ <b>A</b>	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
S A S A S A S A S A S A S A S A S A S A	· · · · · · · · · · · · · · · · · · ·		N/	/ <b>A</b>	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
Sector Se	ALL PORT		N/	/ <b>A</b>	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
La contra de la co			N/	/ <b>A</b>	Shared Landing?	N/A			
	A LAND AND A LAND	PROW/ADA:	N/	/ <b>A</b>	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	A Start Provide	R304.5.1	N/	/ <b>A</b>	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
the section of the section of the			N/	/ <b>A</b>	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To N		X Walk 2 Direction	N/A
and the second s	X C . C		N/	/ <b>A</b>	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	CONNERY CT	-			X Walk 1 Slope (%)	2.0		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	0.5		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		N	/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
	174				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			NI	/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 1	850.00	~	Obstruction Type	11/A		Storm Grate/Utility Type	11/7
			000.00		Obstruction Type	N1/A		Storm Grate/Othinty Type	<b>NI/A</b>
						N/A			N/A



Yes

Surface Condition? (G/P)

Good