

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: N/A Main Street: MILLENNIUM AV Cross Street: POTOMAC RIVER PY Location: SW **Overall Compliance: No Severity Score:** 12.5 **ADA ID: 99AED2C51C86** Ramp Type: Directional1 Initial Pass/Fail: Fail

**Codes/Mitigation Info/Possible Solution** 

Possible Solutions:

## Field Measurements/Component Compliance



POTOMAC RIVER PY Street 1 Name Stop Condition-Street 1 StopSign N/A Street 2 Name Stop Condition-Street 2 N/A

Remove & Replace Entire Ramp. Surveyor Notes: N/A PROW/ADA: R304.2.2

Yes N/A 1600.00

Compliance Description Data Compliance Description Data 125.0 N/A Grade Break? N/A Ramp Length (in) N/A 68.0 N/A Yes Ramp Width (in) Grade Break Slope (%) 0.0 N/A No Ramp Slope (%) 10.1 Grade Break XSlope (%) 0.0 Ramp XSlope (%) 1.4 Flare Type LT N/A N/A Flare Type RT N/A Flare Slope LT (%) N/A N/A Flare Slope RT (%) 0.0 Flare Traversable LT? N/A N/A Flare Traversable RT? N/A 0.0 N/A DWS Provided? Landing Length (in) N/A N/A **DWS Contrast?** Landing Width (in) 0.0 N/A Landing Slope (%) 0.0 N/A DWS Length (in) N/A 0.0 N/A DWS Full Width? Landing X Slope (%) N/A Landing Curb? (Y/N) N/A N/A DWS Offset LT (in) N/A Shared Landing? N/A N/A DWS Offset RT (in) N/A **Gutter Ponding?** 0.0 N/A Gutter Slope (%) N/A Gutter Lip Ht (in) 0.0 N/A Gutter X Slope (%) N/A Painted X Walk1? Road Slope (%) Yes 5.4 To SE X Walk 1 Direction Road X Slope (%) 2.2 X Walk 1 Width (in) 72.0 Clear Space? N/A X Walk 1 Slope (%) 5.4 N/A N/A Clear Space to XWalk (in) X Walk 1 X Slope (%) 2.2 N/A Storm Grate/Utility Hazard? N/A Yes Ramp inside XWalk1? Storm Grate/Utility Type N/A Any Obstructions? N/A **Obstruction Type** Surface Condition? (G/P) Yes Good N/A N/A Curb Slope (%) 7.5





Total Cost:

