cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 27362	Main Street: STONEPATH_LN			eet:	SUNBOW_LN	Location:	NE		
ADA ID: 99DEC9C7AEEA	Ramp Ty	Ramp Type: BlendTrans1 In			ail: Fail Overall C	o Severity Score:	10		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:	<u>(</u>	Compliance Description		Data Complia		ance Description	Data
1125		Remove & Replace Curb Ramp	With N	I/A	Ramp Length (in)	49.0	Yes	BlendTrans Slope (%)	4.2
		Two New Directional Ramps or		lo	Ramp Width (in)	46.5	Yes	BlendTrans XSlope (%)	3.7
		Equivalent.	Ν	I/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
hould be			M	I/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			1	I/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			٩	I/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
STIONERSTIN AN -5.		Surveyor Notes:	1	I/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
AND IN 6		N/A	٩	I/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
the second second			1	I/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			1	I/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
3			1	I/A	Shared Landing?	N/A			
		PROW/ADA:	1	I/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1	Ν	I/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	1	,	1	I/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To S		X Walk 2 Direction	N/A
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	STONEPATH LN	-			X Walk 1 Slope (%)	4.9		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	4.0		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		M	I/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	4.0		Clear Space?	N/A
					Road X Slope (%)	4.9	N/A	Clear Space to XWalk (in)	N/A
			١	I/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	200.00		Obstruction Type			Storm Grate/Utility Type	
1					••	N/A			N/A
							I		







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

13.6