



# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 49390	Main Street: DISTRICT_DR	Cross Street: SHORTHORN_ST	Location: NW
ADA ID: 9A38FF85DAD7	Ramp Type: Combination1	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 46.25

Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	Possible Solutions:			<b>Compliance</b>	<b>Description</b>	<b>Data</b>	<b>Compliance</b>	<b>Description</b>	<b>Data</b>
	<b>Remove &amp; Replace Entire Ramp.</b>			N/A	Ramp Length LT (in)	62.5	N/A	Ramp Length RT (in)	48.0
				Yes	Ramp Width LT (in)	60.0	Yes	Ramp Width RT (in)	60.0
				No	Ramp Slope LT (%)	11.1	No	Ramp Slope RT (%)	10.1
				No	Ramp XSlope LT (%)	2.4	Yes	Ramp XSlope RT (%)	0.5
				N/A	Ramp Length (in)	72.0	Yes	Ramp Slope (%)	4.5
				No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	8.6
	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	<b>DWS LIP 1.0"</b>			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
PROW/ADA:			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
<b>Not Found, R304.5.1, R304.5.3, R304.3.2</b>			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
			N/A	Shared Landing?	N/A				
			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
				X Walk 1 Direction	To S		X Walk 2 Direction	N/A	
				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
				X Walk 1 Slope (%)	8.1		X Walk 2 Slope (%)	N/A	
				X Walk 1 X Slope (%)	0.8		X Walk 2 X Slope (%)	N/A	
			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
				Road Slope (%)	N/A		Clear Space?	N/A	
				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
						N/A	Any Obstruction?	N/A	
							Obstruction Type	N/A	
						N/A	Storm Grate/Utility Hazard?	N/A	
							Storm Grate/Utility Type	N/A	
			Yes	Surface Condition? (G/P)				Good	
				Curb Slope (%)				14.0	
Street 1 Name				None					
Stop Condition-Street 1				DISTRICT DR					
Street 2 Name				N/A					
Stop Condition-Street 2				N/A					
Total Cost:				\$	1800.00				
									

Street 1 Name	None
Stop Condition-Street 1	DISTRICT DR
Street 2 Name	N/A
Stop Condition-Street 2	N/A

Total Cost: \$ 1800.00

